

## ASBESTOS MANAGEMENT PLAN



Once re- inspected insert new inspection date / if removed or encapsulated write sufficient details in action box (i.e removed by M H Goldsmiths on 18/02/2015) Attach any relevant airtests

Branch: Elstree Film Studios Ltd

Re-Inspection Carried out by: Darren Sham

Date of Survey: 22/01 – 02/02/2015

Date of Previous Inspection / Survey: 2005

Date of Latest Inspection: 02.02.15

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
001	John Maxwell, Second floor, room 28, window sill	Chrysotile		✓	Label and inspect annually
002	John Maxwell, second floor, tea room, sink pad	Chrysotile		✓	Label and inspect annually
010	John Maxwell, first floor, room 18, window sill	Chrysotile		✓	Label and inspect annually

Sheet 1 of 1

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
022	Andrew Mitchell, first floor, corridor 2, infill panels	Amosite	✓		Inspect annually
023	Andrew Mitchell, first floor, corridor 2, above room 6, bulk head	Amosite		✓	Label and inspect annually
024	Andrew Mitchell, first floor, corridor 4, above cupboards, bulk head	Amosite		✓	Label and inspect annually
025	Andrew Mitchell, first floor, staircase to plant rooms, ceiling tile	Amosite	✓		Inspect annually
026	Andrew Mitchell, second floor, duct vent 2, distribution board, fuse carrier	Chrysotile		✓	Seal distribution board label and inspect annually
027	Andrew Mitchell, second floor, duct vent, under ducting, debris	Chrysotile		✓	Environmental clean immediate area
028	Andrew Mitchell, second floor, boiler room, fuse carrier	Chrysotile		✓	Encapsulate, label and inspect annually
029	Andrew Mitchell, second floor, landing, ceiling tile	Amosite		✓	Label and inspect annually
036	Enigma, Unit 4, pipe insulation	Amosite		✓	Encapsulate, label and inspect annually

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
038	Enigma, unit 7 plant room walls, debris	Amosite		✓	Removal
039	Enigma, unit 7, fuse box, textile	Chrysotile		✓	Remove discarded fuse then seal distribution board label and inspect annually
041	Enigma, unit 7 plant room walls, debris	Amosite		✓	Removal
042	Enigma, unit 5, electric cupboard walls	Amosite		✓	Repair, encapsulate, label and inspect annually
044	Workshop 10, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
045	Workshop 11, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
046	Workshop 9, void between workshop and w/c, pipe insulation	Amosite		✓	Label and inspect annually
047	Workshop 9, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
048	Workshop 8, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
050	Workshop 8, main area, sink pad	Chrysotile		✓	Label and inspect annually

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
051	Workshop 5, external vertical cladding, cement	Chrysotile		✓	Label and inspect annually
052	Workshop 5, external roof sheets, cement	Chrysotile		✓	Label and inspect annually
054	Workshop 3, external roof sheets, cement	Chrysotile		✓	Label and inspect annually
055	Workshop 3, external gable end, vertical cladding, cement	Chrysotile		✓	Label and inspect annually
057	Workshop 2, external gable end, vertical cladding, cement	Chrysotile		✓	Label and inspect annually
058	Workshop 2, external roof sheets, cement	Chrysotile		✓	Label and inspect annually
059	Workshop 1, gable end and side wall, vertical cladding, cement	Chrysotile		✓	Label and inspect annually
060	Workshop 1, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
070	Workshop 1, external roof, cement sheet	Chrysotile		✓	Label and inspect annually
071	Workshop 1, gable end and side wall, vertical cladding, cement	Chrysotile		✓	Label and inspect annually

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
073	Ancillary block north, central staircase, ground floor riser, debris	Crocidolite		✓	Environmental clean immediate area
074	Ancillary block north, ground floor riser, outside room 12, debris	Crocidolite		✓	Environmental clean immediate area
075	Ancillary block north, ground floor riser, outside room 13, debris	Crocidolite		✓	Environmental clean immediate area
076	Ancillary block north, ground floor riser, outside room 14, debris	Crocidolite		✓	Environmental clean immediate area
077	Ancillary block north, ground floor riser, outside room 16, debris	Crocidolite		✓	Environmental clean immediate area
078	Ancillary block south, staircase riser, debris	Crocidolite		✓	Environmental clean immediate area
079	Ancillary block north, first floor corridor, ceiling void, cable insulation	Chrysotile		✓	Label and inspect annually
081	Ancillary block north, first riser, between w/c's, cement pipe	Chrysotile		✓	Label and inspect annually

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
082	Ancillary block, second floor, 9b louvers ceiling, boarding	Amosite		✓	Encapsulate, label and inspect annually
084	Ancillary block north, plant room, duct gasket	Chrysotile	✓		Inspect annually
085	Ancillary block north, plant room corridor, cement pipe	Chrysotile	✓		Inspect annually
086	Ancillary block north, corridor, opposite electrics, boarding	Amosite		✓	Label and inspect annually
087	Ancillary block north, stage 7, plenum & louver, ceiling board	Amosite		✓	Encapsulate, label and inspect annually
088	Ancillary block north, Ground floor riser, next to w/c's, debris	Crocidolite		✓	Environmental clean immediate area
089	Ancillary block north, stairwell above entry door, infill panel	Amosite		✓	Label and inspect annually
090	Stage 7, gantry staircase on steel columns, debris	Crocidolite		✓	Encapsulate, label and inspect annually
091	Stage 7, fire exit lobby, floor tile	Chrysotile		✓	Label and inspect annually

Sample N°	Location of Sample	Type of Asbestos	Sample Labelled		Action Required
			yes	no	
092	Stage 8, Store room office, floor tile	Chrysotile		✓	Label and inspect annually
097	Underground car park, Durasteel doors	Amosite		✓	Label and inspect annually